

# General Environmental Incident Summary

**Incident:** 5227      **Date/Time Notice:** 9/14/2016      1524      **DEM Incident No:**  
**Responsible Party:** Plains Marketing  
**Date Incident:** 9/13/2016      **Time Incident:** 22:20      **Duration:** 1 minutes  
**County:** Williams      **Twp:** 155      **Rng:** 103      **Sec:** 21      **Qtr:** SW  
**Lat:** 48.22745      **Long:** -103.94110      **Method:** Navigation quality GPS  
**Location Description:** 8 miles north of Hwy 2 on 151st Ave NW, West of Williston, ND

**Submitted By:** Daniel Holli      **Affiliation:** Plains Marketing  
**Address:** P.O. Box 708  
**City:** Belfield      **State:** ND      **Zip:** 58622

## Received By:

**Contact Person:** Daniel Holli  
P.O. Box 708  
Belfield, ND 58622

**Distance Nearest Occupied Building:** 1 Miles      **Release Contained:** Yes

**Type of Incident:** Truck overfill

**Description of Released Contaminant:** Crude Oil condensate

**Volume Spilled:** 1.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

Truck driver overfilled truck while loading condensate at the OneOk State Gas Plant

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soil

## Action Taken or Planned:

Condensate was contained on site and excavated for disposal.

**Wastes Disposal Location:** Chimney Butte Landfarm.

## Agencies Involved:

## **Updates**

---

**Date:** 9/14/2016    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

According to the report 1 barrel of crude oil condensate was released onto the ONEOK State Gas Plant facility. Incident will be followed up when quarterly inspection is undertaken. Report states release was contained on site. More follow-up needed.

---

**Date:** 11/3/2016    **Status:** Correspondence

**Author:** Suess, Bill

**Updated Volume:**

**Notes:**

Site will be inspected during quarterly site visits.